
Make Work Order List

Building

System, Subsystem or Component

Investigation Depth

Central Butte Royal Manor

A1030

Slab on Grade

Cursory examination

Recommendations

Patch and repair as required, tentative repour 2006

Contion Status

8 inch with thickened edge, #12 300 o.c.e.w., Broomed finish,
Bad Spalding 80% of area, some rebar exposed and rusting.