

Building Assessment Information for Central Butte Royal Manor

Record #:	Section Code:	CBRM	Remaining Service Life:	Over 15 Years
1	System	Building Overview	Action Priority:	Code Upgrade
			Rating:	Good
	Investigation Depth		Author:	T Ross
	Detailed examination		Comment Code:	Detail
	CONDITION OR STATUS:			
	Roof on building will need possible changing			
	RECOMMENDATIONS			
	Investigate cost and impact on roof upgrade			