

Physical Condition / Adequacy by Building/Floor/Dept

Building
Floor
Department

Central Butte Royal Manor

Main

Administration / Human Resources

Room	Flooring Type Condition	Wall Finish Condition	Ceiling Finish Condition	Window Condition	Window Treatment Type Condition	HVAC Type Ventilation Level	Plumbing Fixture	Lighting Lighting Level	Phone Outlet	Adequate Power Outlet	Data Outlet	Sufficient Space For Function	Space Appropriate For Function	Space Utilization
CBRM100	Carpet 2	C.T. & Wallboa 3	Exposed 3	Both 3	More Tha 2	Free Stan 2	Assist Tub	Incandesc 3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	1	3
<i>Area:</i> 87.4	<i>Functional Use:</i> Office/Stor.		<i>Standard Area:</i> 0						<i>Physical Condition Rating</i>		<i>Adequacy Rating</i>			
									2.57		2.00			
<i>Physical Conditions Comments</i>	<i>Adequacy Comments</i>													
HRAdmin	2.00	3.00	3.00	3.00	2.00	2.00		3.00		2.57		2.00		
CBRM01	2.00	3.00	3.00	3.00	2.00	2.00		3.00		2.57		2.00		
CBRM	2.00	3.00	3.00	3.00	2.00	2.00		3.00		2.57		2.00		